

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 14, Township 134 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 7-21-93 Placed a 3/4" x 24" REBAR WITH ALUMINUM CAP STAMPED
DATE "DNR SURVEY MARKER", UP 0.3'

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

SFT00039.04.00.01
J.B.M. AUG. 1993

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pommeroy 8-25-93
SIGNATURE DATE

Registration No. 17005

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER 351918
County of CASS

I hereby certify that this document was filed in the Co. recorders office at 4:26 P.M. on the 14th day of October A.D., 1993

County Recorder Claudia Kaylar
By NS, Deputy

DOCUMENT NO. 351918

North Quarter Corner Section 14, Township 134 North, Range 30 West

The DNR Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Cass County Highway Engineer

1868 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and marked the following bearing trees:

Pine 8" N 22° E 21 lks., Pine 13" N 4 1/2° E 65 lks.

1993 July, the DNR Bureau of Engineering conducted a search for this corner but found no evidence of a monument or the government bearing trees. Located a east-west tree to tree fence and a down fence running south, no fence posts. Talked with area landowner L. Muelbauer, who pointed out the vicinity of the corner and said a previous owner - P. Souba showed him this area and thought he had seen a marker at one time but could not find it. Checked this area over with a electronic metal locator, but found nothing. Computed the lost position for this corner and found it to be:

2644.99 ft. from adjoining section corners

24 ft. south of east-west tree to tree fence

42 ft. east of down fence south

Analysis of the available information led the DNR Bureau of Engineering to conclude that the lost position should be used for the corner. The fences in the area do not appear reliable enough to mark the section lines.