


T. 142 R. 28 M. 5th Coordinates: X _____ Y _____

NW 1/16 Corner common to sections 25



25

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 8/1919
 Original monument 1"x 36" I.P. w/Brass cap
 E.G. Harrington, U.S. GLO

NE 1/16 S25
 1919

Original Evidence Found

Year of search 1919 by Horst
 Monument found GLO Brass Cap
 Survey Rec. #435, Bk C, pg 344

Bearing Trees

Species	<u>Maple</u>	<u>Ash</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>N 38° E</u>	<u>S 18°45' W</u>
Distance	<u>83 links</u>	<u>35 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 8/1919 By E.B. Horst, LS 376, Deputy
 Location filed: Survey Record #435, Book C, pg. 344 and Ditch Monument: U.S. I.M. Ditch Shelf 5, Book 34, page 9, states At Sta. 59317.0 U.S. I.M. N.E. 1/16 sec. cor. Wagon trail left 15' N. 1/2 of Rt. Of way cleared.

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 4/1952 By H.J. Curo, LS 3417
 Location filed: Curo Book 285, pages 38 and 39
 Monument: Find IM bent take it up straighten it up and put it back in same hole it came out of go E. work instrument on line between said IM and IM on shore of Boy Lake.

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 8/1966 By R.F. Schneider, LS 5740
 Location filed: Certificate of Survey and notes for Harker, #5414
 Monument: Indicates GLO pipe in place and witnesses as follow.
 10" Maple, S 38° W, 77.2'
 7" Red Oak, N 45° W, 45.9'
 12" Maple, N 37° E, 54.6'

1/1968, R.F. Schneider, LS 5740
 Certificate of Survey in Gov't Lot 1, #5415
 Indicates an iron pipe monument at corner.

10/1982, G.H. Stevenson, LS 12684
 Survey for Drennen, #8616
 Indicates a U.S.G.L.O. Brass Cap Mon. at the corner.

8/1985, C.R Krause, USFS
 Book 1, page 50
 Found GLO iron pipe, cap missing, down 6" in road, GLO witnesses gone, new witnesses as follows.
 11" Maple, S 40° W, 77.6'(1966)
 4" Red Oak, N 3° W, 35.1'

11/1992, T.L. Freeman, LS 21367
 Certificate of Survey for Rose, #8615
 Indicates a monument found at the corner.

Evidence of Subsequent Corner Restoration Found

Year of search 7/1995 By T.L. Freeman, LS 21367
 Location filed: Revised Certificate of Survey for Harker,
 Monument: Indicates iron pipe monument at the corner.

6/1997, C.R. Krause, USFS T142N R28W
 Book 1, page 50 NE 1/16 S 25
 Set 2"x 2' galvanized iron pipe with 1997
 brass cap in place of GLO iron, down USFS
 12" in Co. Rd. #128, Magnet below
 monument and witnessed as follows.
 12" Maple, S 40° W, 77.57'(1966) to spike
 2'x 2' Rock, N 32° W, 55.01' flat top
 9.5" Maple, S 7° E, 69.95' 60d spike

9/2000, T.L. Freeman, LS 21367
 Certificate of Survey for Kube, #988
 Indicates GLO brass cap monument found at the corner.

5/2005, R. Main, USFS,
 Field Book 1, page 50
 Indicates Corner located with Global Positioning System(GPS),
 the 1966 Maple witness is a snag.

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 6/2018 By CCHD/SO

Year of search _____ By _____

Location filed: #2018.016

Location filed:

Monument: Found USFS brass cap monument prior to reconstruction of Co. Rd. #128, , down 0.7', 1', +/-, N. of centerline, removed monument and witness as follows.
Maple stump, S 40° W, 77.5'(1966)
8" Red Oak, N 3° W, 35.24'(1985) 16d duplex nail, up 1.0', W.
2'x 2' Rock, N 32° W, 55.01'(1997) flat top, X near center
10" Maple, S 7° E, 69.95'(1997) 60d spike, up 3.3', E. side
6" Maple, S 32° W, 89.66' 16d duplex nail, up 1.0', W. side

Monument:

