

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST Corner of Section 34, Township 145, Range 28, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On 5/26/82 placed a county cast iron monument at position  
DATE  
determined by corners found in plat of Bena.

## SKETCH OF REFERENCE TIES



U.S. FOREST

ROAD

N & D in  
7" Cedar  
S 10° W  
25.61'

N & D in  
8" Cedar  
S 40. E  
41.00'

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

263901

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Sony H. Atkinson  
SIGNATURE

7-22-82  
DATE

Registration No. 12684

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:15 A. M. on the 22 day of July A.D., 1982

County Recorder Beneath Hendricks  
By MS, Deputy

DOCUMENT NO. 263901

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" Tamarack N 20 E 13 links, 6" Tamarack S 4 E 18 links, 6" Tamarack N 60 W 16 links, and 5" Cedar S 85 W 19 links.
- 1906 Plat of the Village of Bena was filed. The plat was surveyed by James Middleton. The plat shows the position of this section corner.
- 1907 County Surveyor's Record Book B pages 323 to 327 show survey by John Curo. His notes show all four original bearing trees found green and plainly marked. He notes that the trees are somewhat out of place with the original calls. He sets a small iron pin for the corner.
- 1936 U.S. Forest Service records show the following: J.A. Gjelhaug found a 1" x 18" iron pipe at the corner and took the following ties: 4" Tamarack S 31-30 E 18.5', 10" Tamarack N 14-41 E 18.9', and 10" Tamarack N 53-40 W 15.5'.
- 1978 R.F. Schneider, RLS #5740, searched for the corner and found a 1" iron pipe laying in the ditch on the north side of east-west forest road. No other evidence was found and the position of where the pipe had been could not be determined.
- 1982 We again searched for the corner and found no evidence. A traverse was then run around the  $SE\frac{1}{4}$  of the  $SE\frac{1}{4}$ , Sec. 27, locating the 1/16th corners set by Middleton in 1906. From this information and the distances given on the plat of Bena a position for the corner was established. This position fell in the center of the east-west forest road. We dug a 4' x 4' hole to a depth of 3' and found no evidence of the corner. This road runs through a swamp and at the 2' to 3' depth we hit cordoroy logs. The fill of the road was full of old tin cans and wire. I determined that the corner was obliterated and that the location was evidenced by the 1/16th irons in the plat of Bena. I then set a county cast iron monument at this position down 6" in the road.