

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 30, Township 144, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 3/3/81 found a GLO brass cap monument as set in 1930 from
DATE
original bearing trees.

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ray H. Stevenson 9-11-82
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

264956
OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:17 A .M. on the 14 day of Sept A.D., 1982

County Recorder Bertha Hendricks
By MS, Deputy

DOCUMENT NO. 264956

Statement of Evidence:

- 1875 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 12" Spruce S 67 E 27 links and 20" W. Pine N 83 W 54 links.
- 1930 U.S. General Land Office dependent resurvey reestablished this corner from remains of original bearing trees found as follows: 24" Dead W. Pine N 83 W 54 links with "BT" scribe and Spruce stump, badly rotted, S 67 E 27 links. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 14" Bur Oak S 61 3/4 E 283 links and 16" Oak S 24 1/2 W 174 links.
- 1970 U.S. Forest Service records show the following: C. Schluter found the GLO brass cap monument and both 1930 bearing trees.
- 1975 U.S. Forest Service records show the following: C. Krause found the GLO brass cap monument and both 1930 bearing trees. Also found rotted and burned pine stump in bad shape with no marks at bearing and distance for original bearing tree.
- 1981 U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 5". The following bearing trees were found: 20" Oak S 25 W 114.8' with blaze overgrown and Oak stump (windfall) S 62 E 188.8' with blaze overgrown. Two new bearing trees were marked and are shown on this certificate. Steel sign posts were set 2.75' north and 2.9' south of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Sept. 7 I visited the corner and found items as per the 1975 & 1981 USFS reports. I accepted the monument as marking the perpetuated position of the original corner based on the 1930 GLO resurvey.