



8 0 1 0 1 8 5
Tx:4007179

A000562184

OFFICE OF COUNTY RECORDER
CASS COUNTY MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON
07/28/2010 08:52:26 AM
AS DOC #: A000562184
PAGES: 2 REC FEES: 0.00
KATHRYN M. NORBY
COUNTY RECORDER


Index No L - 5

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 18 ,Township 134 ,Range 30
5TH Principal Meridian, State of Minnesota, County of CASS

At the corner location shown on the sketch

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 9/10/07 Placed a 3/4 INCH X 18 INCH REBAR WITH PLASTIC CAP
DATE
STAMPED "MN DNR LS 16098"



| |
|-------------------|
| CASS COUNTY |
| COORDINATE SYSTEM |
| NAD 83 96 ADJ |
| N = 196128 117 |
| E = 492471 772 |

Azimuths taken with compass

Statement of evidence for this corner location is on back of this page.

JDW - 2/25/08
SFT00039 - 1110

I certify that this document was researched and prepared by me or under my direct supervision

SIGNATURE [Signature] DATE 10/8/08 License Number 16098

Title Land Surveyor Professional Engineer County Surveyor County Engineer

East Quarter Corner Section 18, Township 134 North, Range 30 West

The Department of Natural Resources, Division of Lands and Minerals, contacted the following office for information regarding this corner:

MN Secretary of State
Cass County Surveyor's Office
Kramer Leas DeLeo
Westwood Professional Services
Widseth Smith Nolting & Associates
Landecker and Associates

1868 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and following bearing trees were marked:

W. Pine 28" East 52 links (34.32')
Poplar 17" S 44°W 50 links (33')

1997 In June, Landecker and Assoc. surveyed a parcel in Government Lot 2 of section 17. The survey shows an iron pipe at this corner at the lost position between the Northeast and Southeast corners of section 18. A distance of 2641.85' is shown to each corner. The survey shows an iron pipe at the southwest corner of GL 2, 3933.11' easterly of this corner.

2007 In September, the DNR survey crew searched for evidence of this corner. No evidence was found. A 3/4" x 24" iron rod with a plastic survey cap with LS 16098 was set at the lost position for the corner. Ties were taken.

Fd. Monument at SW corner GL 2 bears S89°10'51"E 3931.06'
Southeast Corner Section 18 bears S01°23'01"W 2639.70'
Northeast Corner Section 18 bears N01°23'01"E 2639.70'

For more information on our survey in this area, please contact MN DNR, Division of Lands and Minerals, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56401