

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Patrick A. Trotter

Patrick A. Trotter

Date: 2-14-2011 License No: 41002
41002

A000568497
OFFICE OF COUNTY RECORDER
CASS COUNTY MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON
02/23/2011 07:53:25 AM
AS DOC #: A000568497
PAGES: 2 REC FEES: 0.00
KATHRYN M. NORBY
COUNTY RECORDER

EAST QUARTER Corner of Section 25, Township 138, Range 31, 5th P.M.

On 11-29-2010 found a 1"Ø IRON PIPE W/DAMAGED CAP STAMPED "ULTEIG"


left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____

SKETCH OF REFERENCE TIES

Corner Index: **T-25**

Not to Scale



Statement of evidence for this corner position is on the back of this page



Statement of Evidence

**East quarter corner, Section 25, Township 138 North, Range
31 West, 5th Principal Meridian, Cass County, Minnesota**

1865 – Original U.S. Government Survey establishing this corner was performed. A wood post was set marking its location from which the following witnesses were established:

| | | |
|---------------|-------------|----------|
| 8" Tam. | S 18° E | 18 links |
| 4" Balsam Fir | S 62 1/4° W | 4 links |

1914 – John Curo performs survey of east line of Section 25 as recorded in County Survey Record Book "B", pages 49-53, Survey Record No. 248 and finds no evidence of corner. Field notes in Curo book 97, page 84 made not mention this corner.

1921 – E.B. Horst performed a section subdivision of Section 25 as recorded in County Survey Record Book "D", pages 14-15, Survey Record No. 497 recorded as Document No. 66924, and noted in Curo book 53, page 102. A 2" x 48" iron was placed by single proportion method utilizing the found NE and SE corners of Section 25.

2010 – Patrick Trottier, PLS 41002, found a 1" iron with damaged plastic cap, on which could be read "ULTEIG". Trottier contacted Ulteig Engineering, who provided no additional data after a record search. Iron found lies in centerline of road and distance measurements north to NE corner 25 and south to found 1/16th corner fit 1921 reported distances. Iron with damaged cap accepted as perpetuation of original corner, from which the following witnesses were established

| | | |
|--------------|---------|-------------|
| 6" Poplar | S 32° E | 133.62 feet |
| 2" Wood Post | S 14° W | 115.72 feet |
| Power Pole | N 38° E | 50.58 feet |