

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 21, Township 141, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 9/16/80 found a GLO marked brass cap monument in good condition.
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

263905

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Bary H. Stevenson 4-30-82
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:35 A.M. on the 22 day of July A.D., 1982

County Recorder Dorothy Herdwick

By MS, Deputy

DOCUMENT NO. 263905

Statement of Evidence:

- 1873 U.S. General Land Office survey (set wood post) for this corner and marked the following bearing trees: 10" B. Oak N 56 E 57 links and 26" Y. Pine S 31 W 23 links.
- 1918 U.S. General Land Office dependent resurvey reestablished this corner by proportional measurement between section corners. No evidence was found of the original post or bearing trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 7" W. Pine S 41-15 E 131 links.
- 1980 USFS technician W. Olson found the GLO brass cap monument in place in good condition. No evidence of the 1918 bearing tree was found. Three new bearing trees were marked and are shown on this certificate. A steel sign post was set 4.0' north of the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Jan. 29, visited corner area and found items as per the 1980 USFS report. Snow depth prevented a detailed search for evidence of the 1918 bearing tree.
- Rough chainage made by W. Olson in 1980 from the NE corner of Sec. 21 checked well with the GLO distance. Accepted monument as marking the same position as when set in 1918.
- 1982 On April 21, USFS technician C. Krause rechecked corner for evidence of the 1918 bearing tree. He found no positive evidence of the W. Pine at the record bearing and distance. The monument was up 8" and was securely in place. It did not appear to have been disturbed.

12.25 - 25 - 35
NE - SE - 3N
35 - 3N