

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 4, Township 142, Range 26, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 2/4/87 placed a 2" x 48" Galv. iron pipe with 3" marked brass cap
DATE

SKETCH OF REFERENCE TIES



ALL TREES ARE DOUBLE BLAZED, SCRIBED & PAINTED RED WITH 54-3 TAG

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page. 295275

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Mary A. Stoumen 2/21/87
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 2:00 P.M. on the 25 day of February A.D., 19 87

County Recorder Clondine Kayler

By MS, Deputy

DOCUMENT NO. 295275

Statement of Evidence:

- 1872 - U.S. General Land Office survey (set wood post) for this corner and marked the following bearing trees: 4" Spruce N 34° W 18 links and 4" Birch N 32° E 15 links.
- 1986 - County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1986 - U.S. Forest Service office in Cass Lake was contacted for information and no resurvey information was found on this corner. They searched briefly for corner in 1964.
- 1986 -
1987 - We traversed the east line of Sec. 4. (This line had been previously traversed by the U.S. Forest Service in 1979). We measured 5982.50 feet between section corners. This distance is 522.98 feet longer than the GLO distance of 5459.52 feet. We determined the lost position of the corner, on line at the proportional distance between section corners. We searched an area 300 feet, more or less, north and south of this lost position. No evidence was found of the corner. The lost position fell in a low area. This was not called in the original notes. However, with the large discrepancy in the distance, the few physical calls were of no use in resetting this corner. I determined the corner to be lost and set a U.S. Forest Service monument, 2½" x 48" iron pipe with marked brass cap. Steel sign posts were set 5.0' EAST and 5.0' SOUTH.