

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 22, Township 143 N., Range 26 W., 5th P.M.


CASS

STATE OF MINNESOTA, County of _____

At the corner location shown on the sketch:

- On 5/27/87 found a P.K. Nail at center line of Roads
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 11/3/87 placed a 1 1/4" x 1 1/4" x 20 PERFORATED STEEL TUBE WITH
DATE ALUMINUM CAP STAMPED "DNR SURVEY MARKER", DOWN 0.1'

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

J.A.G. 6/26/87
FILE G-321

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Walker 2-1-88
SIGNATURE DATE

Registration No. 16098

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

303530

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office of H.W.R. .M. on the 4 day of April A.D., 19 88

County Recorder Clairine Kayler

By ms, Deputy

DOCUMENT NO. 303530

North Quarter Corner Section 22, Township 143 North, Range 26 West

- 1872 The U.S. General Land Office set a post and recorded two bearing trees.
- 1900 The U.S. Corp of Engineers describes this corner as known.
- 1916 A survey on page 171 in Book "C" by E. B. Horst in the County Recorder's Office states that a post was found and two new witness trees were tied in for reference.
- 1925 A Cass County Land Corner Record Sheet discloses that the County Highway Department used the corner and located the two 1916 ties inplace.
- No Date The same tie sheet discloses that on page 45 in Book 82, George Ralph used the corner and measured three ties. Two of the ties are the 1916 ties.
- 1959 The DNR set a railroad spike at a road intersection and measured three reference ties.
- Circa A County Road No. 65 R/W map assumed the corner and called it a spike
1962 inplace. Three reference ties were measured.
- 1987 The DNR found a P.K. nail and replaced same with a standard DNR Monument as shown and described on this certificate. No previous ties remain.