


Index No. X 9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 32 Corner common to sections 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument Post

Species	Bearing	Trees
<u>TAM</u>	<u>TAM</u>	
<u>18"</u>	<u>22"</u>	
<u>N 86° E</u>	<u>N 62° W</u>	
<u>23 LKS.</u>	<u>19 LKS.</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By John Curro  
Location filed COUNTY SURVEY RECORD BOOK "A" P. 581-515  
Monument FIND OLD GOVT B.T.: 22" TAM N 62° W 19 LKS.

Evidence of Subsequent Corner Restoration

Year of search 1/23/91 By David Landecker  
Set 1 1/2" x 42" iron pipe 4" above surface.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Spruce</u>	<u>Elm</u>	<u>Balsam</u>	
<u>18"</u>	<u>13"</u>	<u>5"</u>	
<u>West</u>	<u>N 52° E</u>	<u>S 30° E</u>	
<u>271.84'</u>	<u>73.68'</u>	<u>133.28'</u>	

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
3-24-92 Cert Filed by David Landecker  
RLS 17008 Doc # 336118

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_