


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 139 R. 29 M. 5th Coordinates: X _____ Y _____
N14 22 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	<u>N. PINE</u>	_____
Diameter	<u>5"</u>	<u>17"</u>	_____
Bearing	<u>N77W</u>	<u>S52W</u>	_____
Distance	<u>22 LKS</u>	<u>52 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1975 By Co. H&T Dept
Location filed Co Rd # 49
Monument 1 1/2" i.p. in place

Evidence of Subsequent Corner Restoration

Year of search 1987 By Gary Stevenson
Doc # 300480 - Corner Certificate
set 2x2x36" sq steel post w/ aluminum cap at lost position
other pin (used by others) sets S180 25' 50" E 58.62'

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Poplar</u>	<u>J. Pine</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>NW</u>	<u>North</u>	<u>NE</u>
Distance	<u>74.2'</u>	<u>81.3'</u>	<u>77.3'</u>

Bearing Trees, Reference Objects

<u>Birch</u>	<u>Birch</u>	<u>Oak</u>	<u>sign post W 1'</u>
<u>9"</u>	<u>6"</u>	<u>6"</u>	
<u>N50W</u>	<u>N10W</u>	<u>N40E</u>	<u>R. 10' w post E. 2'</u>
<u>85.24'</u>	<u>65.25'</u>	<u>104.35'</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1987
Doc # 300480