


T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>24"</u>	<u>18"</u>
Bearing	<u>N 8 E</u>	<u>N 80 W</u>
Distance	<u>71 LKS</u>	<u>24 LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1987 By W. Buckler  
Location filed \_\_\_\_\_  
Monument Set 3/4" iron pipe at lost position.

Evidence of Subsequent Corner Restoration

Year of search 9/03 By Landecker & Assoc  
Found 3/4" IP capped RLS 9672 and 1987 witnesses. A CofL was filed.

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>20</u>	<u>28"</u>
Bearing	<u>West</u>	<u>N 40° E</u>
Distance	<u>23.70'</u>	<u>19.78'</u>

Bearing Trees, Reference Objects

T-9

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared #474531  
Filed at CCRO

By \*21367  
Date 10/7/03