


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey	
Year surveyed	<u>1872</u>
Original monument	<u>POST</u>
Bearing Trees	
Species	<u>CEDAR</u>
Diameter	<u>16"</u>
Bearing	<u>N 30W</u>
Distance	<u>15 LKS</u>

Original Evidence Found	
Year of search	By _____
Monument found _____	
Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration
 Year surveyed 1986-1987 By Gary Stevenson
 Location filed Doc # 295277 - corner certificate
 Monument find 6" x 60" concrete monument w/ cap.
certificate made to update 1963 certificate

Evidence of Subsequent Corner Restoration
 Year of search 1963 By Bill Okerman
Corner Certificate
find stump w/ scribe S W, decayed stump NW
also 1" p.p. along C/P, w/ squared post along pipe scribed
"1453", and also spring leaf by pipe
Set 6" x 60" concrete cylinder w/ disc.

Bearing Trees, Reference Objects			
Species	<u>Balsam</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>N 20° W</u>	<u>N 38° E</u>	<u>S 81° E</u>
Distance	<u>8.85'</u>	<u>73.90'</u>	<u>48.80'</u>

Bearing Trees, Reference Objects		
Cedar	Cedar	Cedar post
10"	8"	4x4x60
S 81° E	N 38° E	west
48.8'	73.9'	2.5'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963
certificate - Gary Stevenson 1987 - update
Doc. # 295277