

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST Corner of Section 33, Township 144, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 1/29/81 found a GLO brass cap monument as set in 1930 from
DATE
evidence of original bearing trees.
 - left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Dan A. Stenman 9-11-82
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

264961
 OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:22 A.M. on the 14 day of Sept. A.D., 1982

County Recorder Beverly Hendricks

By MS, Deputy

DOCUMENT NO. 264961

Statement of Evidence:

- 1875 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 10" Tamarack S 89 3/4 E 477 links, 4" Cedar N 80 W 240 links, 8" Tamarack N 87 E 437 links, and 4" Cedar S 55 W 238 links.
- 1930 U.S. General Land Office dependent resurvey reestablished this corner from two original bearing trees found as follows: 12" Tamarack N 88 E 439 links and 16" Tamarack S 89.3/4 E 474 links. Both trees had old blaze marks. No evidence found of the two Cedar trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 4" Tamarack N 27 1/2 E 19 1/2 links, 4" Tamarack S 76 1/2 E 18 links, 4" Tamarack S 14 1/2 W 16 links, and 6" Tamarack N 50 1/4 W 21 links.
- 1934 U.S. Forest Service records show the following: CCC records show brass cap monument found and four 1930 bearing trees.
- 1968 U.S. Forest Service records show the following: L. Martinson found brass cap monument.
- 1981 U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition but leaning. Straightened iron. The following bearing trees were found: Tam. stump N 28 E 12.9' with some scribe visible (1930), Tam. stump S 77 E 11.9' (1930), and Tam. stump East 312.8' (1875). Four new bearing trees were marked and are shown on this certificate. Steel sign posts were set 2.8' east and 2.9' north of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1930 by the GLO resurvey based on bearing tree evidence.