

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Reference to
 Meander No. 25 Corner of Section 4, Township 141, Range 31, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On 5/4/82 found a iron set by 1925 County survey lying flat
 having ^{DATE} been moved by ice action and lake bank change.
 - left monument as found, lowered monument, removed monument (explain)
- On 8/14/85 placed a 2"x36" concrete filled galvanized iron
^{DATE} pipe with 3" marked brass cap on section line.

SKETCH OF REFERENCE TIES



Bearings are approximate

Statement of evidence relative to this corner location is on back of page. 284231

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Nancy H. Stevenson 8/21/85
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 3:30 P.M. on the 6 day of Sept. A.D., 19 85

Register of Deeds Claudia Kayler

By MS, Deputy

DOCUMENT NO. 284231

STATEMENT OF EVIDENCE

- 1873 - U.S. General Land Office survey set a wood post for this corner and marked the following bearing trees: 3" Birch N 39 W 29 links and 3" Birch S 70 W 25 links.
- 1925 - County resurvey plat "E-51" was filed showing the subdivision of Section 4, 141-31. Survey was signed by John M. Greene. Survey shows an iron monument set at this corner on line between the section corners on the west side of Long Lake 643.10 feet from the North Quarter corner of said Sec. 4.
- 1982 - I ran a traverse along the north line of said Sec. 4 and at this corner found a 2½" galvanized iron pipe as set by Greene lying flat in sand ice ridge. Greene did not set this corner by any proportion method since the GLO distance across Long Lake was found to be considerably less than shown in the GLO notes. I set a 1½" iron pipe on line between the North Quarter corner and the Northeast corner of said Section 4 in the sand ridge 625.59 feet east of the quarter corner. Corner iron set is for reference marking the section line only and is not the meander corner.
- 1985 - We replaced the iron set in 1982 with a U.S. Forest Service monument being a 2"x36" concrete filled galvanized iron pipe with a 3" brass cap. A steel sign post was set west of the corner.