

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 33, Township 134 N., Range 32 W., 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 8/29/89 found a 1/2" IRON PIPE, FLUSH  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On            placed a             
DATE

## SKETCH OF REFERENCE TIES



### BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

DDS 10-27-89  
 FILE: A-49196

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Walker 12-28-90  
SIGNATURE DATE

Registration No. 16098

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 3:50 P. M. on the 2 day of January A.D., 19 91

County Recorder Cloniece Kayler  
 By ms, Deputy

DOCUMENT NO. 325962

North Quarter Corner Section 33, Township 134 North, Range 32 West, 5th P.M.

The following offices were contacted for information on this corner:

Secretary of State  
Wadena County Highway Department  
Cass County Surveyor  
Cass County Highway Department  
Landecker and Associates, Inc., Pequot Lakes, MN  
Roy A. Smith and Associates, Inc., Detroit Lakes, MN  
Comstock and Davis, Little Falls, MN  
Richard Howe, Alexandria, MN

- 1870 This corner was established by the U.S. General Land Office and monumented with a post and witnessed by the following bearing trees:  
8" B. Pine, South 12° West, 13 links  
9" B. Pine, North 43° East, 16 links
- 1980 April 14, a tie sheet from Landecker and Associates has a 2" iron found in north-south gravel road and gravel road east. Monuments were left as found.
- 1980 May 6, a section map prepared by Landecker and Associates has a distance of 2624.11 feet from the north quarter of Section 33 to the northwest corner of Section 33.
- A tie sheet from the Cass County Highway Department has a 1/2" I.P. at the quarter corner with two ties that match with Mr. Landecker's.
- 1987 May, a tie sheet from the Cass County Surveyor's Office has a 1/2" iron at the intersection of a north-south road and road east, with ties that match with Mr. Landecker's.
- 1988 A worksheet by Roy A. Smith and Associates has a 5/8" iron which checks with the county ties. Mr. Smith also has a pin at centerline, centerline.
- 1988 In August, the DNR Bureau of Engineering found a 1/2" inside diameter iron pipe with ties that check with the county ties. An 8"x8"x4" stone was found underneath the said iron. The DNR Bureau of Engineering also found a 3/4" rebar at the intersection of centerline of roads north-south and east.

The distance from the 1/2" iron pipe to the northwest corner of Section 33 is 2623.65 feet.

The DNR Bureau of Engineering accepted the iron pipe as the quarter corner.

Traverse information is available from the DNR Bureau of Engineering.