


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 33, Township 134 N., Range 32 W., 5th P.M.
 STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 8/30/88 found a OLD CORNER FENCE POST (DOWN 0.5')
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 8/30/88 placed a 1½"x1½"x20" PERFORATED STEEL TUBE WITH
DATE ALUMINUM CAP STAMPED "DNR SURVEY MARKER"

SKETCH OF REFERENCE TIES



NOT TO SCALE

AZIMUTHS OBSERVED
WITH A COMPASS

Statement of evidence relative to this corner location is on back of page.

DDS 2/16/89
FILE A - 49196

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Walker 12-28-90
SIGNATURE DATE

Registration No. 16098

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorder's office at 3:55 P. M. on the 2 day of January A.D., 1991

County Recorder Claudia Kayler
 By me, Deputy

DOCUMENT NO. 325963

East Quarter Corner Section 33, Township 134 North, Range 32 West, 5th P.M.

The following offices were contacted for information on this corner:

Secretary of State
Wadena County Highway Department
Cass County Surveyor
Cass County Highway Department
Landecker and Associates, Inc., Pequot Lakes, MN
Roy A. Smith and Associates, Inc., Detroit Lakes, MN
Comstock and Davis, Little Falls, MN
Richard Howe, Alexandria, MN

1870 This corner was established by the U.S. General Land Office and monumented with a post and witnessed by the following bearing trees:

6" Aspen, North 36° East, 27 links
8" Aspen, North 23° West, 35 links

1988 The Department of Natural Resources, Bureau of Engineering, made a search for the corner but no evidence of the original government survey was found. An old corner fence post was found down 0.5 of a foot at the intersection of old fences east and south. These fences were estimated to be about 50 years old. From the point of intersection of said fences it is 2616.30 feet to the northeast corner of Section 33 and 2722.77 feet to the southeast corner of Section 33.

According to an area landowner, Mr. Farbor, who is approximately 50 years old, a new east-west fence was put in at a convenient location north of the old east-west fence. The old corner fence post was accepted as marking the obliterated position of the corner and a DNR Survey Marker was set as shown on the face of this certificate.

Traverse information is available from the DNR Bureau of Engineering.