

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard Southeast Corner of Section 31
Township 145 N , Range 27 W , 5th P.M.
STATE OF MINNESOTA, COUNTY OF CASS



A000601098

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

3/20/2014 11:04:12 AM

AS DOC #: A000601098

PAGES: 3

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR Dep

Page 1 of 3
A000601098


On 05/18/2010, found a(n): 3" Brass Tablet, Standard GLO Monument 5.5" Concrete Cylinder

- left monument as found
- removed monument (explain)
- lowered monument
- raised monument

On _____, set a(n): _____

See "Statement of Evidence" for further details (on back)

(reserved for recording data)



"SKETCH OF REFERENCE TIES" (not to scale - bearings are magnetic)

Ties are measured to center of monument unless otherwise noted.

UNITS = Metric English

UTM COORDINATES, ZONE 15

Northing: 17197964.760

Easting: 1358421.112

NAD 83/1996 HARN Adjustment.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Ross Wamre
signature

6/25/13
date

Ross Wamre, Minnesota License No. 45334



STATEMENT OF EVIDENCE: Standard Section Corner common to Sections 31 and 32 of Township 145 North, Range 27 West of the 5th Principal Meridian.

1871; This corner was originally established by G. R. Stuntz for the GLO. His field notes indicate this corner position, witnessed by:

- B. Pine 6" North 61° West, 68 links (44.88')
- B. Pine 5" North 28° East, 183 links (120.78')

1937; GLO dependent resurvey of the Eleventh Standard Parallel North, along the South boundary of Township 145 North, through a portion of Range 26 West and through Range 27 West, 5th Principal Meridian. Hal D. Craig, found no remaining evidence of the original standard corner reestablished this corner's position by proportionate measure and set a concrete monument 2' long, 6" diameter, 20" in the ground with a brass tablet, 3 1/4" diameter, witnessed.

- Tamarack 12" North 81° East, 234 links (154.44')
- White Pine 8" North 41° West, 96 links (63.36')

1941; Clifford Smith, USFS, 874 forms, found a brass capped pipe in good condition level with ground witnessed. Information on file with the USFS office in Cass Lake.

- Tamarack 8" North 18° West, 80 links (52.80')
- Tamarack 10" North 72° East, 101 links (66.66')

1981; K. Whitehorn, RLS# 14677 found GLO brass tablet in concrete on a small island in swamp, flush with ground and witnessed. USFS Book 1 of Township 145 North, Range 27 West, page 24.

- White Pine 12" North 41° West, 96 links (63.36', 1937 Tie)
- White Pine 12" North 63° West, 20.34'
- Tamarack 9" South 57° East, 4.77'

1983; G. Robertson and Don Harmon visited the corner position and found much blowdown from the storm including the 1937 white pine and 1981 white pine. Robertson and Harmon found the monument and re-witnessed the corner with the following bearing trees with a double blaze, FS 54-3 signs and a 60d spike in base of blaze. USFS Book 1 of Township 145 North, Range 27 West, page 24.

- Black Spruce 5.5" North 55° West, 33.52'
- White Pine 16.6" South 67° West, 31.39'

2010; A Kadrmas, Lee & Jackson survey crew found a 6" concrete monument with a 3" Brass Tablet and witnessed. Witnesses found and established as shown on the face of this certificate.

2012; Ross Wamre, RLS #45334, after analysis of record and survey information accepts this monument as the correct perpetuation of the corner.

Contacts pertaining to this corner are as follows:

Cass County Recorder's Office



Cass County Engineers Office
Cass County Surveyors Office
Northern Engineering and Consulting Inc.
United States Forest Service
MnDOT – District Office 2
Bureau of Indians Affairs – Bemidji
Bureau of Land Management's (BLM) Northeastern States Field Office