


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 137 R. 29 M. 5TH Coordinates: X NE 33 Corner common to sections 27, 28, 33, 34 Y _____



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	BL. PINE	BL. PINE	Y. PINE	BL. PINE
Diameter	6"	6"	12"	6"
Bearing	N43E	N38W	S31W	S64E
Distance	23 LKS	37 LKS	36 LKS	50 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK 'A' P. 318-328
Monument FIND STUMP 2 OF OLD GALT B. TS: 6" BL. PINE N43E 15.2', BL. PINE 6" N38W 24.4', 12" W. PINE S31W 23.8', 6" BL. PINE S64E 33' SET 7/8" X 24" IRON IN 1910 PULL I.P. SET 8X8X36" CEMENT POST

Evidence of Subsequent Corner Restoration

Year of search _____ By ROAD SURVEY
COUNTY BOOK 'C' P. 477 2X 48" IRON MONUMENT

Bearing Trees, Reference Objects

Species CFP also on microfilm -
Diameter hack roll 115 BK 85 P. 275
Bearing N38-20E
Distance 38.75'

Bearing Trees, Reference Objects

V-13

Subsequent Corner Restoration

Year surveyed 1922 By Miss. Hwy. Dept.
Location filed R/W map in Recorder's office - Pine River to Requet.
Monument Found concrete monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - C.J. BARK - ASST HWY ENGINEER - 1922
Set 6" x 6" concrete monument. TIES: 2" hollow iron pipe NE 46.7'; 2" hollow iron pipe SE 46.7'; 2" hollow iron pipe NW 46.7'; 2" hollow iron pipe SW 46.7'.

1917 Co. DITCH SURVEY BK (9) BOX 3 OF Co. DITCH SURVEY BOOKS, PG 3+4

1998-CCSO

Ed. in place 2" Alum. cap monument down 0.4' in bit. Top is marred + unreadable @ 115 + 6' top 50'

- Corner GPS 9/18/02 CCSO
Spk in remains of Alum cap talsper, down 0.4, on E & S

4" Bur Oak	88.05'	N 35° E
10" R. Oak	110.33'	N 60° E
P.P.	127.00'	S 12° E