


Index No. N19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup> 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Bearing Trees	
Species <u>Ironwood</u>	<u>5H</u>
Diameter <u>8"</u>	<u>6"</u>
Bearing <u>S10E</u>	<u>N70E</u>
Distance <u>27LKS</u>	<u>39LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SECRETARY OF STATE

Monument PROPORTIONAL POSITION - NO ORIG. EVIDENCE  
SET 1 X 3/4" I.P. W/GRASS CM

1/4 - 514  
523  
1918

Evidence of Subsequent Corner Restoration Found

Year of search 1972 By William Okerman

Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species <u>ASH</u>	<u>BL. OAK</u>
Diameter <u>6"</u>	<u>6"</u>
Bearing <u>N38 1/4 E</u>	<u>S67 W</u>
Distance <u>33 LKS</u>	<u>113 LKS</u>

Bearing Trees, Reference Objects

<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
<u>7"</u>	<u>11"</u>	<u>5"</u>
<u>N 79 W</u>	<u>N 44 W</u>	<u>N 9 W</u>
<u>50.40'</u>	<u>83.80'</u>	<u>55.60'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1974 Certificate - William Okerman

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_