


Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 54H Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>4"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>N23W</u>	<u>N17E</u>	<u>S35W</u>	<u>S22E</u>
Distance	<u>23 LKS</u>	<u>19 LKS</u>	<u>16 LKS</u>	<u>19 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1910 By G&O
Location filed SEC. OF STATE
Monument FIND 3" WOOD POST AND STUMPS OF ALL 4
COURT B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1989 By DAVID LANDECKER
Set 3/4" x 5' aluminum rod with 3'
fluted top and stamped aluminum cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Maple	Poplar	Burr Oak	Spruce
<u>5"</u>	<u>7"</u>	<u>4"</u>	<u>7"</u>
<u>S76W</u>	<u>N28E</u>	<u>N48E</u>	<u>S24E</u>
<u>74.39'</u>	<u>96.48'</u>	<u>89.90'</u>	<u>86.03'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 312153

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____