


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
E 114 13 Corner common to sections 13 AND 18 - 141 - 30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Bearing Trees

Species	<u>ASPEN</u>	<u>BIRCH</u>	_____
Diameter	<u>7 1/2"</u>	<u>8"</u>	_____
Bearing	<u>S 72 E</u>	<u>N 85 1/2 W</u>	_____
Distance	<u>11 LKS</u>	<u>5 LKS</u>	_____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1988 By David Landecker
 Location filed _____
 Monument Set 2" x 24" iron monument with brass cap.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>Maple</u>	<u>Burr Oak</u>
Diameter	<u>10"</u>	<u>8"</u>	<u>7"</u>
Bearing	<u>N 58 W</u>	<u>S 5 E</u>	<u>N 40 E</u>
Distance	<u>60.35'</u>	<u>34.19'</u>	<u>23.09'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311072

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____