


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Species	FIR	Bearing FIR	Trees FIR	ASPEN
Diameter	6"	5"	5"	8"
Bearing	N40E	S41E	S51W	N38W
Distance	5 LKS	10 LKS	17 LKS	27 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY BOOK "C" P415
Monument FIND LARGE BOULDER W/ CROSS MARK IN RD. FOR CORNER
COUNTY RESURVEY 1921 "E-2" I.M.

(C.F.P) Bearing Trees, Reference Objects

Species	FENCE CORNER	TELEPHONE	C.F.P.
Diameter	8"	15"	10"
Bearing	N1E	S44E	S43W
Distance	20'	26.75'	34.5'

Evidence of Subsequent Corner Restoration

Year of search 1973 By CURT KRAUSE
U.S. F.S. LOCATED IRON UNDER BLACKTOP AT P.I. ROADS E-W - S AND FENCE NORTH
1982 - Co. HWY & SURVEYOR - FIND SNAKE FOR P.I. R.O.S.
- NO IRON DUG FOR BOULDER - FIND 2 1/2 x 4' BOULDER WAS DISTURBED BY ROAD MAKING - PIECES BROKEN OFF -

Bearing Trees, Reference Objects

AND WAS TIPPED OVER - NO SIGN OF A "X"
REMOVED ON ADVICE OF Co. ENGINEER (ASSISTANT)
HE DID NOT WANT IT IN FILL - FIND IT DOWN
2.5'

V-17

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument CORNER GPS 4/4/03 CC50
CC50 4/4/03 Found brass cap, USES
MARY FLUSH, 4' ± S. of E Co. Rd. #4,
1' ± E. of E #130. 1986 witnesses
are good.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1986
Doc. # 291470
Set corner by proportionate measure from
corners in SEC 26
Set 2"x24" galv. 11 P. w/brass cap.
6" W. oak N40°W 98.26'
5" W. oak N20°E 88.94'
4" W. oak S27°E 163.37'
6" Aspen S62°W 127.60'

Nov. 2004 T. Freeman #21367
Cert. of Survey shows monument found