


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SOUTHEAST Corner of Section 10, Township 139, Range 29, 5th P.M.
 STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 8/21/86 found a RAILROAD SPIKE
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 8/21/86 placed a CAST IRON COUNTY MONUMENT
DATE

SKETCH OF REFERENCE TIES



NOTE: ALL TIE DISTANCES WERE TAKEN TO A SQUARE DISC PLACED IN THE SIDE OF THE TREE OR PK NAIL IN POLE.

Statement of evidence relative to this corner location is on back of page. 297693

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David A. Sandaker 8/29/86
SIGNATURE DATE
 Registration No. 17008
 Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Recorder's office at 10:15 A. M. on the 22 day of June A.D., 19 87
 COUNTY RECORDER Clouline Kayler
 By ms, Deputy
 DOCUMENT NO. 297693

STATEMENT OF EVIDENCE

Southeast corner, Section 10, Township 139 North, Range 29 West, Cass County, Minnesota.

The original government survey was done in 1865, a post was set establishing the corner thereof.

1910 - A. W. Moulster finds stake set and original Northwest bearing tree. Plat Ponto Lake Cemetery. County survey book B, page 159.

1924 - John Greene. Plat of East Shore on Ponto Lake, said Section 10.

1942 - John Curo find corner and makes new ties, County survey book D, page 310

1952 - Harold Curo finds drift bolt and 1942 Curo ties to power and anchor pole, County survey book D, page 423

1972 - R. F. Schneider surveys Plat of Norway Shores.

1975 - Myron Landecker, RLS #7452, Landecker & Associates, Inc. finds corner and surveys Plat of Ponto Lake Cemetery First Addition.

1986 - David Landecker, RLS #17008, Landecker & Associates, Inc. finds railroad spike and Curo ties referenced in 1942 and 1952 surveys and also plat ties of both Moulster and Myron Landecker surveys of which all fit corner position. Landecker & Associates, Inc. therefore accepts this corner as a perpetuation of the Southeast corner of said Section 10.