

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 28, Township 143, Range 25, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:


On 1989 found a 2 1/2" x 28" ALUM. BLM MONUMENT
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

NOT TO SCALE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page. 326338

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter P. Green 1-22-91
 SIGNATURE DATE

Registration No. 11395

Land Surveyor

County Surveyor

OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:15 A.M. on the 25 day of January A.D., 19 91

County Recorder Clondine Kayler
By ms, Deputy

DOCUMENT NO. 326338

Statement of Evidence:

R-13 NE Cor. of Sec. 28, T143N., R25W.

1872 Original survey by Hayward and Griffin, set a wood post and marked bt's as follows:

10" Birch	S58W	11 lks
10" Birch	N11W	18 lks
16" Birch	N78E	20 lks
6" Birch	S17E	16 lks

1900 Corp. of Engineers ran an open ended stadia traverse to this corner. They said they found four stump holes.

1976 B.L.M. made a dependent resurvey of part of the township and found a 1" pipe of unknown origin and set a 2-1/2" x 28" aluminum pipe with cap in place of the 1" pipe.

1979-1983 B.L.M. was made aware of the 1900 survey by the Corp. In 1983 they made a corrective dependent survey and moved the monument to a new position determined from remains of original bearing tree stump holes.

1989 The USFS used this monument as part of a traverse around section 28.

1989 Walt Curo and Curt Krause of the U.S.F.S. visited the B.L.M. corner and made a search for original evidence and there was no indication of the ground ever having been disturbed.

1989 Curo Surveying, in corresponding with B.L.M., learned that B.L.M. was only quoting the Corp. of Engineers findings, and that they did not find these stump holes, that they set their corner from a computed position from the Corp's notes.

1990 Walt Curo accepts the B.L.M. monument for the corner as this position was monumented and accepted by the B.L.M. as the true position for this corner and no other evidence remains in this area due to time and logging operations.