

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard South Quarter Corner of Section 31  
Township 145 N , Range 26 W , 5th P.M.  
STATE OF MINNESOTA, COUNTY OF CASS



A000599558

OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON

1/9/2014 1:30:08 PM

AS DOC #: A000599558

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY  
CASS COUNTY RECORDER  
BY SR Dep

On 10/30/2012, found a(n): 2.5" Brass Cap Stamped 1937  
On 2" Iron Pipe 0.4' Up In Swamp


- left monument as found
- lowered monument
- removed monument (explain)
- raised monument

On \_\_\_\_\_, set a(n): \_\_\_\_\_

See "Statement of Evidence" for further details (on back)

(reserved for recording data)

NOTE: Tamarack Swamp Area



### "SKETCH OF REFERENCE TIES" (not to scale - bearings are magnetic)



Ties are measured to center of monument unless otherwise noted.

UNITS =  Metric  English

UTM COORDINATES, ZONE 15

Northing: 17197528.690

Easting: 1387335.822

NAD 83/1996 Adjustment.  
Obtained by RTK GPS observations.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Ross Wamre  
signature

6/6/13  
date

Ross Wamre, Minnesota License No. 45334

Page 1 of 2  
A000599558



**STATEMENT OF EVIDENCE:** Standard Corner to Section 31 of Township 145 North, Range 26 West of the 5<sup>th</sup> Principal Meridian.

**1871;** This corner was originally established by G.R. Stuntz for the GLO. His field notes indicate this corner position was marked with a post, and witnessed by:

Tamarack 8" dia. North 85<sup>o</sup> East, 608 Links  
Tamarack 7" dia. North 75<sup>o</sup> West, 87 Links

**1937;** GLO Dependent Resurvey determined SC ¼ S31 from remains of original BT, set iron post, 3'x 2", with a 2.5" brass cap marked SC ¼ S31 1937, and witnessed by:

Fallen Tamarack 10" dia. North 85<sup>o</sup> East, 608 Links marked ¼ S (original)  
New BT:  
Tamarack 5" dia. North 86 ¾<sup>o</sup> East, 602 Links marked SC ¼ S31 BT  
Tamarack 5" dia. North 65 ¾<sup>o</sup> West, 130 Links marked SC ¼ S31 BT

**2012;** A Kadrmas, Lee, & Jackson survey crew found a 2.5" brass cap stamped 1937 on a 2" iron pipe, 0.4' up in swamp and witnessed with posts. Witnesses established as shown on face of this certificate.

**2012;** Ross Wamre, RLS #45334, after analysis of record and survey information accepts this monument as the correct perpetuation of the corner.

Contacts pertaining to this corner are as follows:

Cass County Recorder's Office  
Cass County Engineers Office  
Cass County Surveyors Office  
Northern Engineering and Consulting Inc.  
United States Forest Service  
MnDOT – District Office 2  
Bureau of Indians Affairs – Bemidji  
Bureau of Land Management's (BLM) Northeastern States Field Office