


# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 18, Township 134, Range 31, 5th P.M.  
STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On Oct., 1993 placed a 1/2" iron pipe monument capped RLS No. 16097  
DATE



Statement of evidence relative to this corner location is on back of page. 357106

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

*[Signature]*  
SIGNATURE

April 13, 1994  
DATE

Registration No. 16097

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of CASS

I hereby certify that this document was filed in the Co. Recorders office at 11:10 A.M. on the 26th day of APRIL A.D., 1994

County Recorder Claudine Kayler  
By N.B. [Signature], Deputy

DOCUMENT NO. 357106

Statement of Evidence:

The Northeast Corner of Section 18, Township 134, Range 31, 5th Principal Meridian, Cass County, Minnesota, was set under the Public Land Survey as a post with four bearing trees in 1869, No traces of post or bearing trees now exist.

County Survey Record No. 193 indicates a boulder found, set from old Gov't Bt's at the northeast corner of Sec. 18. No boulder was foun. Bk A, pg. 473-477

On June 25, 1902, May Township issued a Supervisor's Road order and laid out by survey a 4 rod road centered on the line between Sections 5 and 6, and Sections 7 and 8.

\*\* On April 30, 1971, May Township issued a resolution to close the road running between Sections 7 and 8.

The County Surveyor's Office was contacted and corner card information was obtained.

In 1992, while surveying along the common line between Sections 7 and 8, the area of the obliterated position of the southeast corner of Section 7, being also the northeast corner of Section 18, was searched at the intersection of the centerline of the abandoned Township Road bed and the east-west fence line. The area was probed hand dug, and scanned with a metal detector. No corner evidence was found. A 1/2" iron pipe monument capped RLS No. 16097 was set at this obliterated position and is accepted as the position for the Northeast Corner of Section 18.

\*\* 1915 notes in County Bk. "B", pg. 484-495 indicate N.D. Gorman started survey from corner and ran east. Possible I.M.