



A000615452

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

9/17/2015 10:38:56 AM

AS DOC #: A000615452

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER


BY SR _____ Dep TX#: 125756

Page 1 of 2 A000615452

Index No. A.0-3.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.


Corey J. Hendershott

Date: 08/30/2015 License No: 45353

North Quarter Corner of Section 6, Township 136 North, Range 30 West of the 5th Principal Meridian. County of Cass, STATE OF MINNESOTA.


On May 16, 2015 I searched for Gov't and 1908 evidence, but found none, so set a 3/4"x18" Iron Pipe w/plastic cap 45353 at a Proportional position same as did John Curo did in 1908.

left monument as found; lowered monument; removed monuments (explain)

On Date.

decl: 1° EAST

SKETCH OF REFERENCE TIES not to scale



Statement of evidence for this corner position is on the back of this page

A.0-3.0

STATEMENT OF EVIDENCE: North Quarter to Section 6, Township 136 North,
Range 30 West, of the 5th Principal Meridian.

Not Set in the Original Surveys 1858 or 1870.

1908; (Dec.) Cass County Survey Record Book "B", Pages 140 – 157, these note states that John W. Curo, Licensed Surveyor establish the position by "LOST" methods. This corner was witness by the following:

1908, Tamarack stump, 10", Nail on Southeast side. No Bearing or Distance given. He states reason "not being necessary".

1908; (Dec.) Curo's Field Book 85, page 260. These note states the same information as what is stated in the County Survey Record "B", pages 140-157, notes.

2014; (Nov) I Corey J. Hendershott, L.S. 45353, Eagle Eye Data Services search for John W. Curo's 1908 Tamarack stump with a nail in the SE side with no luck. So I set a ¾"x 18" Iron Pipe with plastic cap 45353 at a Proportional position. Monument is 1' south of E-W centerline, down 5" below grade. This corner position was witnessed as shown on the face of this document.

I set this corner at a Proportional position.

Cass County South Zone NAD 83 (96)
N 273203.663
E 489355.630