


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Mile Post 5 Leech Lake Reservation Boundary, Township 141 North, Range 28 West, 5th P.M.
State of Minnesota, County of Cass

On 10-4-1990 Northern Lights Surveying & Mapping set a standard brass capped iron pipe at the proportioned position. Said position falls on a line between a proportioned point on the east and west section lines of section 28, T141N, R28W (from GLO original subdivision). The corner was then proportioned between the calculated reservation-township line intersection and the existing Mile Post 2.

SKETCH OF REFERENCE TIES & EVIDENCE



NOT TO SCALE



Statement of evidence relative to this corner location is on the back of this page 326704

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

LaVerne Leuelling
 LaVerne Leuelling
 Registered Land Surveyor No. 18089
 NORTHERN LIGHTS SURVEYING & MAPPING
 Date 1-21-91

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Recorder's office.

Time: 1:40 P. .M. Date: 2/14/91
 Recorder Cloudeine Kaylin
 By ms Deputy
 DOCUMENT NO. 326704

Statement of Evidence

December 1873: C.H.Conger set a wooden post for Mile Post 5 which was 25 chains westerly of a marsh edge and 20 chains easterly from the other edge of the same open marsh. He established the following Bearing Trees:

24" N. PINE
S85°E
350 LINKS (231.00')

January 1874: C.H.Conger in his subdivision of T141N, R28W intersected the reservation boundary 25.33 chains northerly of the SE corner of section 28 and 5.15 chains southerly of the SE corner of section 28.

October 3 & 4, 1990: Northern Lights Surveying & Mapping searched for Conger's bearing tree after calculating a "lost" position and finding that the position fell along the prolongation of a 250 foot extent of old fence posts which ran from the east edge of the open marsh on a bearing of N80°W. The position for the pine bearing tree would have fallen on a higher point on the south edge of the marsh. Unfortunately no evidence of the BT was found and the corner was set "lost".

6" Aspen	5" Aspen	5" Oak	Steel Sign Post
S53°E	S43°W	S87°W	S80°E
72.48'	37.27'	35.16'	6.0'