

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Northeast Corner of Section 34, Township 135 N, Range 31 W, 5TH P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE \_\_\_\_\_
- left monument as found,  lowered monument,  removed monument (explain)
- On 9/26/95 Placed a R.R. Spike on centerline East-West Road in line  
DATE 12/1/98 Replaced R.R. Spike with "MNDNR" Survey Marker  
with Fence South.

SKETCH OF REFERENCE TIES



NAD83 CASS CO.  
COORDINATES

N 214,721.54

E 476,261.03

Abstract Document  
#441860

Azimuths observed with Compass

Statement of evidence relative to this corner location is on back of page.

DATE 10/22/99  
FILE WMA01198

I hereby certify that this document and the data contained herein was prepared by me or under

my direct supervision.

John D. Walker 5/13/01  
SIGNATURE DATE

License Number 16098

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. recorders office at 3:00 P .M. on the 16th day of Oct. A.D., 2001

County Recorder Kathryn M. Norley  
By John F. Maeder, Deputy

DOCUMENT NO. 441860

**Northeast Corner Section 34, Township 135 North, Range 31 West**

The Department of Natural Resources, Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State  
 Cass County Surveyor  
 Widseth, Smith and Nolting of Brainerd  
 Landecker and Associates of Pequot Lakes  
 Landecker and Associates of Walker  
 Central Minnesota Surveying

- 1870 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and the following bearing trees were marked:
- W. Birch 10" S 32° E 27 links
  - W. Birch 12" N 30° E 333 links
  - W. Birch 11" S 35° W 40 links
  - Maple 6" N 41° W 38 links
- 1995 The DNR survey crew searched for evidence of the corner in the centerline of an old east-west road. A fence line was found going south and west just to the south of the road. The corner was assumed to be at the intersection of the fence extension and the centerline of the old road grade. A railroad spike was set and located by GPS.
- 1998 The DNR survey crew removed the railroad spike and replaced it with a MNDNR Survey Marker to mark the assumed location of the corner.
- Northeast Corner Section 35 bears S 89°53'17" E 5267.36'
  - North Quarter Corner Section 34 bears N 89°24'02" W 2675.54'
  - Northeast Corner Section 27 bears N 00°41'38" W 5315.72'
  - Southeast Corner Section 34 bears S 00°39'25" W 5372.54'

For more information on our survey in this area please contact MN DNR, Bureau of Engineering, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56425