

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH SIXTEENTH Corner of Section 29&30, Township 144, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 3/3/81 found a GLO brass cap monument as set in 1930.  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Gay H. Stevens 9-11-82  
SIGNATURE DATE

Registration No. 12684

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

264954  
 OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:15 A.M. on the 14 day of Sept. A.D., 19 82

County Recorder Donald Henderson

By MS, Deputy

DOCUMENT NO. 264954

Statement of Evidence:

- 1930 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" Maple N 38½ E 24 links and 8" Maple N 71½ W 55 links.
- 1970 U.S. Forest service records show the following: C. Schluter found GLO brass cap monument.
- 1975 U.S. Forest Service technician C. Krause found the corner monumented with a GLO brass cap monument in good condition up 8". The following bearing trees were found: 15" Maple N 38½ E 15.8' with scribe visible and 12" Maple N 71½ W 36.3' with scribe visible. Three new bearing trees were marked: 7" Basswood N 28 E 36.4'; 15" W. Spruce S 78 W 67.4', 12" Basswood N 75 W 11.5'. Steel sign posts were set 3.6' south and 3.2' west of the corner.
- 1981 U.S. Forest Service technician G. Brama found the GLO brass cap monument in good condition and the bearing trees as reported and marked in 1975 by C. Krause. The W. Spruce had fallen over. One new bearing tree was marked and is shown on this certificate along with the other live bearing trees.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Sept. 7 I visited the corner and found items as per the 1975 & 1981 USFS reports. I accepted the monument as marking the same position as when set in 1930 by the GLO resurvey based on bearing tree evidence.