

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 29, Township 145, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 10/24/79 found a GLO brass cap monument as set in 1933.
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Sandy A. Stevenson SIGNATURE 9-15-82 DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

279382
OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:20 P. P.M. on the 10 day of Dec. A.D., 1984

County Recorder Claudia Kayler
By MS Deputy

DOCUMENT NO. 279382

Statement of Evidence:

- 1874 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" Blk. Oak N 45 W 62 links, 8" Sugar S 76 W 38 links, 24" W. Pine N 14 E 90 links, and 6" Elm S 26 E 82 links.
- 1933 U.S. General Land Office dependent resurvey reestablished this corner by proportionate distance. No evidence found of the original corner or bearing trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 6" W. Pine N $38\frac{1}{4}$ E 107 links, 7" W. Ash S $76\frac{3}{4}$ E 43 links, 12" W. Ash S $19\frac{1}{2}$ W 91 links, and 6" W. Pine N $50\frac{1}{2}$ W 73 links.
- 1934 U.S. Forest Service records show the following: J.A. Gjelhaug found the GLO monument and four bearing trees.
- 1979 U.S. Forest Service technician M. Hayes found the corner monumented with a GLO brass cap monument set in concrete cylinder up 3" above ground in good condition. The following bearing trees were found: 16" W. Pine N 38 E 70.75', 8" Ash (broke off) S 77 E 28.4', 16" B. Ash S 19 W 60.25', and 20" W. Pine N 55 W 48.3'. One bearing tree was marked and is shown on this certificate. A steel sign post was set 1.6' west of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1933 by the GLO resurvey based on bearing tree evidence.