

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 32, Township 141 N, Range 31 W, 5th P.M.


STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 11/12/84 placed a 2½ inch by 5 foot long galvanized pipe with a 3 inch
DATE brass cap, stamped as shown, up 18 inches.

5¼° East declination

SKETCH OF REFERENCE TIES
not to scale



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Anthony E. Kerich 12/12/84
SIGNATURE DATE

Registration No. 12266

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

280495

OFFICE OF THE REGISTER OF DEEDS
County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 10:00 A.M. on the 25 day of February A.D., 19 85

Register of Deeds Clondine Kayler

By MS, Deputy

DOCUMENT NO. 280495

Statement of Evidence:

EAST QUARTER CORNER OF SECTION 32, TOWNSHIP 141 NORTH,
RANGE 31 WEST OF THE 5th PRINCIPAL MERIDIAN.

1873 - The original Public Land Survey was run by P.H. Conger. A wood post was set to mark the corner and two bearing trees were recorded as accessories:

40" W. Pine S 70°E 20 links (13.2')
16" N. Pine S 20°E 30 links (19.8')

1961 - R.H. McDonald found a Forest Service poster on West side of 30 inch White Pine saying corner is 50 chains (33') North found nothing at that location.

1973 - Curtis R. Krause of the U.S. Forest Service found a tag on Pine snag. Using land ties of original survey from Quarter corner to Northeast corner to North, this position is 600 feet, more or less, to far South. Went 600 feet North for search but found nothing. He stated that corner may fall in woods trail North-South, there are living White and Red Pine to West of road on ridge above swamp also many burned pine stumps in area.

1984 - Kerick Surveying, Inc., Bemidji, MN. subdivided Section 32 for the U.S. Forest Service. We ran a traverse close to a search area, two areas were thoroughly searched one was on line split between the computed position for the SE cor. of the Section and the NE corner of Section 32, the other position was 40 chains South of the Northeast corner of the Section, on the theory that original Survey was run from North to South one direction only. We found nothing at either location. Also contacted Walter Curo R.L.S. from Hackensack MN. he did a survey in the South $\frac{1}{2}$ of the Southeast $\frac{1}{4}$ of section 32. He also stated that he search both locations for the Quarter corner that he determined the position to be lost but did not set a monument there. Although the better evidence points to a proportion 40 chains south of the NE corner. I decided to set corner lost or on line split between NE and SE of Section 32 because the West Quarter corner of this Section was also set this way and also to create harmony with other surveys and the pattern of the adjacent Sections that have been subdivided. Set a U.S.F.S. 3 inch brass capped monument stamped accordingly and recorded new accessories that appear on this certificate. One other reason for setting this corner in the lost position instead of a proportioned distance was the fact the physical ties called for in the Government notes are nowhere near close, especially the call to the North Shore of Tenmile Lake.