

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 32, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 46° 59' 12.433"
 Longitude: 94° 21' 54.377"


On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 3/31/89 placed a 2 inch by 48 inch iron pipe with brass cap
DATE
 and plastic base with magnet.

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree.



Monument is located $\pm 90'$ Southerly of waters edge of Moccasin Lake.

Monument Stamped
 T 141 N R 29 W
 $\frac{1}{4}$
 S32+S33
 1989
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

312155

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 5-12-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:05 P.M. on the 15 day of May A.D., 1989

County Recorder Claudia Kayh
 By ms, Deputy

DOCUMENT NO. 312155

Statement of Evidence:

East Quarter Corner of Section 32, Township 141
North, Range 29 West, Cass County, Minnesota

X-9 141-29
Bk.6 Pg.18

1873 P.H. Conger, U.S. Deputy Surveyor, surveyed and ran the common line between Section 32 and 33. His notes and plat do not indicate that a corner post was set in the original survey for this position.

1973 Myron L. Landecker, Registered Land Surveyor Number 7452, surveyed the plat of Ondarkos Moccasin Lake Acres. In performing the survey for this plat, Mr. Landecker established the East Quarter corner of this section at its lost position between the Northeast and Southeast corner of the section. No other original corners or evidence was found at the time whereby his decision was made. No Quarter corner monument was set.

1980 Walt E. Curo, Registered Land Surveyor Number 11395, surveyed part of Government Lot 6 and part of the Southeast of the Southeast, Section 32, for the plat of Moccasin Bay. In performing his survey for this plat, Mr. Curo basically followed the same methods as described in the above survey performed by Landecker. Mr. Curo, however, established a monument at the Quarter corner position and it is labeled as the Northeast corner of Government Lot 6 on his plat.

1986 U. S. Forest Service crews set an aerial target in the vicinity of this corner of the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U. S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1989 on March 31 Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet at the lost position as noted above. New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.

In performance of this survey I have found original evidence of the Meander Corner Number 18 lying between the East Quarter Corner and Northeast corner of the section. This meander corner as recovered then establishes a different determination for the subdivision of Section 32 then determined previously by Landecker and Curo as prescribed by law. The position of the Quarter corner being established by single proportionate measurement between Meander Corner Number 18 and the Southeast corner of said Section 32 is therefore in a position different then determined by the previous Landecker and Curo survey. Their corner position is approximately 100 feet Southerly and 13 feet Westerly of the position established and monumented as noted on this certificate.