

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section 17, Township 145, Range 31, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On 3/8/94 placed a 2" X 30" Square tube with MN/DOT Cast Iron Cap.  
DATE  
Top of monument 0.3 feet above ground.

### SKETCH OF REFERENCE TIES



Trees and Pole double blazed and scribed.

Statement of evidence relative to this corner location is on back of page.

357119

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Robert W. Murray 3-28-94  
SIGNATURE DATE

Registration No. 15483

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER

County of CASS

I hereby certify that this document was filed in the Co. Recorders office at 1:20 P. M. on the 26th day of APRIL A.D., 1994

County Recorder Claudine Kaylan

By NS MACROFILM, Deputy

DOCUMENT NO. 357119

Statement of Evidence:

**NORTH QUARTER CORNER SECTION 17, TOWNSHIP 145 NORTH  
RANGE 31 WEST, FIFTH PRINCIPAL MERIDIAN**

**1875** The original Public Land Survey was run by Benjamin C. Baldwin. A scribed post was set to mark corner and witness ties were recorded:

**7" Jack Pine S. 20° W. 16 links**

**8" Jack Pine N. 42° E. 21 links**

**1906** John Curo found no evidence of corner and set iron for corner lost on line split between northwest and northeast corners of Section 17 and new witness ties as follows: ( Survey Record Book A, pages 268-269 )

**10" Jack Pine S. 33°27' W. 22.80 feet**

**8" Jack Pine S. 29°30' E. 36.30 feet**

**1912** John Curo found his 1906 iron graded out by railroad and his bearing trees now stumps. ( Survey Record Book D, page 147 )

**1963** Jack Salo, RLS, found no evidence of corner and established position for corner on paper.

**1992** Murray Surveying, Inc., found no evidence of corner and established position for corner as lost at an on line split between the northwest and northeast corners of Section 17.

For information regarding this survey, contact Murray Surveying, Inc., Bemidji, MN.