

410194

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

James Krume 2/12/99
SIGNATURE DATE

Registration No. 23668

- Land Surveyor, Professional Engineer,
- County Surveyor, County Engineer.

OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 120 P M. on the 23rd day of February A.D. 1999

County Recorder Claudine Taylor

By K.F. Deputy

DOCUMENT NO. 410194

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 4, Township 141 N, Range 28 W, 5th P.M.


STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

On 6/26/97 found a 1 1/2 INCH PIPE DOWN 1.0 FOOT
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE



Statement of evidence relative to this corner location is on back of page.

Statement of Evidence: East Quarter corner Section 4, T. 141 N., R. 28 W., 5th P.M.

- 1874 US General Land Office survey set a wood post for this corner and marked the following bearings; 20" Norway Pine N 40 W 65 links, 30" Norway Pine N 69 E 23 links.
- 1918 US General Land Office dependant resurvey found original survey Bearing Ties and set a 1" x 36" Iron pipe with a brass cap, and marked the following bearing; 6" Red Oak N 11 1/2 W 256 links.
- 1998 Minnesota Department of Transportation survey found a 1 1/2 inch pipe, and no B.T.'s. With no previous history of this monument the said survey located the NE corner of section 4 and computed a lost position by single proportion for the E 1/4 section 4, using the 1917 resurvey distances. The computed position fell 2.21 ft. away from the found monument, therefore the 1 1/2 inch Iron Pipe Monument was accepted as the E 1/4 corner of section 4, and the following bearings were marked; Power Pole S 15 W 117.80 ft., 18" Norway Pine S 50 E 59.21 ft., 20" Burr Oak S 25 E 75.50 ft., Steel Witness Sign Post N 90 E 27.60 ft. The Minnesota Department of Transportation accepts this position as the correct location for the corner.

For details and survey analysis, contact The Minnesota Department of Transportation District surveys Office in Baxter, Minnesota.