



A000591536

OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON

4/15/2013 10:53:06 AM

AS DOC #: A000591536

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY  
CASS COUNTY RECORDER

BY SR \_\_\_\_\_ Dep

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Signature: \_\_\_\_\_

James Kramer

Date: 3-19-2013

Reg. No. 23668

NAD 1996 (HARN) CASS COUNTY COORDINATES  
N= 241116.263 E= 431534.589

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


INDEX NO. A-9, Northeast CORNER OF SECTION 5, TOWNSHIP 135, RANGE 32,  
STATE OF MINNESOTA, COUNTY OF CASS

AT THE CORNER LOCATION SHOWN ON THE SKETCH:

- ON 3-19-2013 FOUND A(N) cast iron monument down 8", with car spring on east side.
- LEFT MONUMENT AS FOUND,  LOWERED MONUMENT,  REMOVED MONUMENT (EXPLAIN)
- ON \_\_\_\_\_ DATE \_\_\_\_\_ PLACED A(N) \_\_\_\_\_

### SKETCH OF REFERENCE TIES

Magnetic Declination Assumed 6°30'  
Sketch Not to Scale




**KLD**  
1120 Industrial Park Road SW  
Brainerd, MN 56401  
218-826-5333

**KRAMER LEAS DELEO**  
SURVEYING • ENGINEERING • PLANNING  
BRainerd ST. CLOUD

Note: Monument is 10' E of N-S cl and 2' S of E cl

STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON BACK OF PAGE

Page 1 of 2  
A000591536





Index No. A-9

Statement of Evidence

*Northeast Corner of Section 5, T135N, R 32 W, Cass County, Minnesota*

- 1858 The Original Government Survey was run and a post was set to mark the corner. Ties were made to four Spruce Pine.
- 1899 Township road order shows no survey. (CCSO corner card)
- 1901 Township road order shows no survey. (CCSO corner card)
- 1985 Terry Freeman, licensed land surveyor, recovered a car spring at the corner location.
- 1986 Terry Freeman, licensed land surveyor, indicates replacing the recovered car spring with a cast iron monument.
- 1987 Walt Curo, licensed land surveyor, indicates recovering a cast iron monument. Ties were made to two Jack Pine and a Norway Pine, a Certificate of Location was recorded as Document No. 297160.
- 2013 Crews from Kramer Leas Deleo searched the area and recovered a cast iron monument, with a car spring located on the east side of the monument. The three 1987 bearing ties were not located. Bearing ties were made to a Red Pine, two Black Pine and a street sign.
- 2013 On February 19, 2013, James Kramer, PLS #23668, analysis of record and survey information indicates the recovered cast iron monument to be the perpetuation of the original corner.