


T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 23 Corner common to sections 14 AND 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Bearing Trees	
Species <u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>7"</u>	<u>7"</u>
Bearing <u>S36W</u>	<u>N3E</u>
Distance <u>6 LKS</u>	<u>19 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By _____
Location filed _____
Monument Co DITCH SURVEY BK 5 BOX 2 OF
Co DITCH SURVEY BOOKS, PG 29

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Evidence of Subsequent Corner Restoration.

Year of search 1985 ~~1987~~ By Freeman
Find 3/4" I.P. w/ RLS cap 9672
I.P. in E-W Rd, fence S, ± 15' E of GRDN.
8-11-87 Set 2" x 18" telescopic monument with
stamped aluminum cap down 1". Located 18'
east of E of road N and E road E-W.

Bearing Trees, Reference Objects

BURR OAK	TR1-RED OAK	TWIN RED OAK	PUR POLE
<u>15"</u>	<u>6" 8" - 8"</u>	<u>5" - 10"</u>	_____
<u>N44W</u>	<u>N23E</u>	<u>S4W</u>	<u>N52E</u>
<u>77.60</u>	<u>94.82</u>	<u>31.20</u>	<u>51.32</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
3-19-90 Cert. Filed by Walter Curo. RLS 11395
Doc # 319093 showing 1987 information