


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument Post

Species	Bearing	Trees	Distance
<u>POPLAR</u>	<u>S 70 E</u>	<u>B. OAK</u>	<u>6 LKS.</u>
<u>POPLAR</u>	<u>N 14 W</u>	<u>B. OAK</u>	<u>37 LKS.</u>
<u>POPLAR</u>	<u>N 30 E</u>	<u>B. OAK</u>	<u>18 LKS.</u>
<u>POPLAR</u>	<u>S 45 W</u>	<u>B. OAK</u>	<u>6 LKS.</u>
<u>POPLAR</u>	<u>N 7</u>	<u>B. OAK</u>	<u>7</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1994 5-31 By John Walker

Placed a 3/4" x 24" rebar w/ alum. cap stamped: "DNR Survey marker" (up 0.2") with lath in woods

2-22-96 Cert. Filed by John Walker, RLS 16098.

Doc #375015

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Maple</u>	<u>Maple</u>	<u>Red Oak</u>
<u>6"</u>	<u>5"</u>	<u>8"</u>
<u>N 81 E</u>	<u>N 42 W</u>	<u>S 48 E</u>
<u>8.22</u>	<u>6.60</u>	<u>4.41</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____