


Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5th Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

	Bearing	Trees
Species	<u>Bl. Pine</u>	<u>Aspen</u>
Diameter	<u>8"</u>	<u>10"</u>
Bearing	<u>S 70 W</u>	<u>S 60 E</u>
Distance	<u>210 LKS.</u>	<u>213 LKS.</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 8/29/88 By John Walker / DNR
 Location filed Cert. Filed Doc. # 325964
 Monument Found 1 1/2" well point with 3"x6"x16" stone.
Set a 1 1/4"x1 1/4"x20" perforated steel tube
with stamped aluminum cap.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

	Bearing	Trees, Reference Objects
Species	<u>Jack Pine</u>	<u>Power Pole</u>
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>340°</u>	<u>44°</u>
Distance	<u>55.70'</u>	<u>61.69'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Oct. 2003 M. Nyberg # 13145
Cert. of Sur. shows iron monument found

1-2-91 Cert. Filed by John Walker / DNR
RLS 16098 Doc. # 325964

Remuneration certificate prepared _____
 Filed at _____

By _____
 Date _____