


T. 136 R. 31 M. 5th Coordinates: X _____ Y _____
N 1/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 9/1870, R. Cronk
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>White Birch</u>	<u>Balsam</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>S 40° E</u>	<u>N 7° E</u>	_____
Distance	<u>30 links</u>	<u>32 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/2014 By P.A. Trottier, LS 41002
Location filed: Certificate of Location
Monument: Set 1/2"x 18" iron pipe, capped RLS 41002 at single proportion position, midway and on line between section corners and witnessed as follows.

Evidence of Subsequent Corner Restoration

Year of search 6/2014 By P.A. Trottier, LS 41002
Location filed: Certificate of Survey for Cass Co. #7431
Monument: Indicates iron monument set, marked RLS 41002

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Oak</u>	<u>Oak</u>	_____
Diameter	<u>20"</u>	<u>18"</u>	<u>10"</u>	_____
Bearing	<u>N 40° W</u>	<u>N 20° E</u>	<u>S 75° E</u>	_____
Distance	<u>8.24'</u>	<u>20.09'</u>	<u>7.11'</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 4/2020 By CCHD/SO
Location filed: #2020.007
Monument: Found 7/8" ODIP, RLS 41002 up 0.2', SW of small flow age and witnessed as follows. 20" Red Oak, N 40° W, 8.24'(2014) duplex nail, up 1.2', N. side 18" Red Oak, N 20° E, 20.09'(2014) duplex nail, up 1.5', E side 12" Red Oak, S 75° E, 7.11'(2014) duplex nail, up 1.4', S. side

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

