


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35 - 13B-30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument POST

Species	Bearing	Trees	
<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
<u>7"</u>	<u>8"</u>	<u>8"</u>	<u>8"</u>
<u>N45 1/2 E</u>	<u>N34 W</u>	<u>S51 W</u>	<u>S 67 E</u>
<u>38 LKS.</u>	<u>34 LKS</u>	<u>22 LKS.</u>	<u>15 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1965 By R.F. SCHWEIDER
 Location filed COUNTY BOOK "D" P. 456
 Monument IRON PIN

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>C. F. P. TELE. POLE</u>		
	<u>SOUTH</u>	<u>37.4'</u>
	<u>N12 1/2 W</u>	<u>36.3'</u>

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

A-17

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument JUNE 2004 B. Grinna # 17253
Cert. of Sur. Shows mon. Found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____ By _____
 Filed at _____ Date _____