


Index No. N11

CASS COUNTY LAND CORNER RECORD

T. 138 R. R9 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1421 Corner common to sections \_\_\_\_\_



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument NOT SET ORIGINALLY.

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CRO  
Location filed COUNTY SURVEY RECORD BOOK B<sup>1</sup> P209-300  
Monument SET 3x3x24" HUB SET 2448" GALV. I.P.  
W/CAP IN CONCRETE PROPORTIONALLY. (INDRY LIKE  
BEQ.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Dec 2002 B. Grivna #17253  
Cert. of Surv. shows Mon. found  
Nov. 2004 B. Grivna #17253  
Cert of Survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_