


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 130 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 4 Corner common to sections 3, 4 AND 33, 34 - 139-32



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1860  
Original monument POST

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>BIRCH</u>	<u>SPRUCE</u>
Diameter <u>15"</u>	<u>8"</u>	<u>7"</u>	<u>8"</u>
Bearing <u>N63E</u>	<u>S51W</u>	<u>N25W</u>	<u>S60W</u>
Distance <u>27LKS</u>	<u>30LKS</u>	<u>163LKS</u>	<u>93LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 2000 JULY By CCSO  
Find. in place; 60d spk., down 9.2' Located  
3' S & M<sup>c</sup>Kinley Rd. EAST & 10' E of E Rd  
SOUTH.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Bearing Trees, Reference Objects**

<u>CM signpost</u>	<u>Fencepost</u>	_____
<u>S 60° W</u>	<u>S 60° E</u>	_____
<u>28.81'</u>	<u>26.17'</u>	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_