


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 21 Corner common to sections 16, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	_____
Diameter	<u>10"</u>	<u>10"</u>	_____
Bearing	<u>N 60 E</u>	<u>S 4 E</u>	_____
Distance	<u>33 LKS</u>	<u>30 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK # 1 862  
Monument Set approx 1/4 Cor. 2 1/2" Peple w/ tag  
tie to 11P - 130' west 141' N

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK # 8  
Find stake and stumps of both B.T.S set 1 1/2 x  
5 1/4" 11P. w/ 2 1/4" Steel Cap

T139  
16  
21  
R25

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Balsam</u>	<u>Balsam</u>	_____	_____
<u>6 1/2"</u>	<u>7"</u>	_____	_____
<u>N 53 E</u>	<u>S 14 E</u>	_____	_____
<u>23.8'</u>	<u>21.5'</u>	_____	_____
<u>Scribed</u>	<u>Scribed</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_