


Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 25 Corner common to sections 24, 25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
<u>5"</u>	<u>6"</u>	
<u>N 5 E</u>	<u>S 15 W</u>	
<u>27 LKS</u>	<u>28 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 2 P. 34
Monument Set approx 1/4 post 2640' from west

Evidence of Subsequent Corner Restoration

Year of search July 2004 By CCSO
Set 7/8" ODIP, up 0.3', 100'± South of track.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>10"</u>	<u>N 20° W</u>	<u>33.64'*</u>
<u>R. Oak</u>	<u>10"</u>	<u>S 71° E</u>	<u>23.69'*</u>
<u>Maple</u>	<u>6"</u>	<u>S 11° W</u>	<u>17.67'*</u>

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____