


Index No. V 17-18

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 31 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>ASPEN</u>	<u>W. BIRCH</u>	_____
Diameter	<u>7"</u>	<u>8"</u>	_____
Bearing	<u>NORTH</u>	<u>S 80 E</u>	_____
Distance	<u>7 LKS</u>	<u>13 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK #3 P. 59
Monument MC IS 3.12 CH East of NE 34 (in lake)

Evidence of Subsequent Corner Restoration

Year of search 7/31/91 By James Nielsen / MN DOT
Found 1 1/4" PIPE
On 2/22/93 set MHD cast iron monument.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Willow</u>	<u>Ash</u>	<u>Ash</u>	<u>Maple</u>
<u>1 1/2"</u>	<u>4"</u>	<u>6"</u>	<u>20"</u>
<u>S 70 W</u>	<u>S 45 W</u>	<u>S 15 E</u>	<u>N 70 E</u>
<u>20.55'</u>	<u>19.20'</u>	<u>10.48'</u>	<u>43.20'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
6-2-93 Cert. Filed by James Nielsen
Doc. # 347760.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____