


Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
N114 1 Corner common to sections LAND 36-140-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN ASPEN _____
Diameter 9" 10" _____
Bearing N3E S7W _____
Distance 12LKS 20LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK#3 P.54
Monument yellow tag on Sq. Poplar tree

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____