


Index No. A5

CASS COUNTY LAND CORNER RECORD

T. 139 R. R7 M. 3TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 6 Corner common to sections 56 and 31, 32-140-27



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1863  
Original monument POST

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Trees	Distance
<u>MAYLE</u>	<u>4"</u>	<u>MAYLE</u>	<u>4"</u>
<u>MAYLE</u>	<u>4"</u>	<u>MAYLE</u>	<u>4"</u>
<u>NB6 1/2 E</u>	<u>50 1/2 E</u>	<u>SR 7 W</u>	<u>N 75 W</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936 By CCC  
Location filed Washburn Lake - BK # 7 P. 22  
Monument Set 4" Pine stake at 80 CH from east

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_