


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. R13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 28 Corner common to sections 21, 22, 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1864  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>B. OAK</u>	<u>B. OAK</u>	<u>ASPEN</u>	<u>ASPEN</u>
<u>6"</u>	<u>12"</u>	<u>20"</u>	<u>8"</u>
<u>N31E</u>	<u>N52W</u>	<u>S12E</u>	<u>S45W</u>
<u>40 LKS</u>	<u>37 LKS</u>	<u>16 LKS</u>	<u>10 LKS.</u>

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-10, E-12"  
Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "C" P. 311 SET 2 1/2' LONG  
1 P. W/ CAD.

Evidence of Subsequent Corner Restoration  
Year of search 1939 By CCC  
Washburn Lake - BK# 13 P. 29.  
gt 5280' from E - set approx. cor.  
BK13 P. 32 gt 5305' from W. temp cor.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>POPCAR STUB</u>	<u>R. OAK</u>	
<u>13"</u>	<u>14"</u>	
<u>N2° 66' W</u>	<u>S65-30W</u>	
<u>21.3'</u>	<u>21.3'</u>	

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

R-13

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search 1999 By Landecker + Assoc.  
Cert. of Survey indicates monument  
found.

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_